


Monday, August 4, 2014

Loudoun County, Virginia www.loudoun.gov

(map not to scale)



PIN 231-38-8886 / Tax Map # /48/A//31//// 112 EDWARDS FERRY RD NE Primary Zoning LB: B1 / H-1 Page No. 1

RECONNAISSANCE LEVEL SURVEY REPORT

DEPARTMENT OF HISTORIC RESOURCE RECONNAISSANCE SURVEY FORM

DHR Idenfication Number: 253-0035-0494

Other DHR Number:

Property Date(s) 1800-1895

PROPERTY NAMES

House, 42 Edwards Ferry Road

Historic

EXPLANATION

09/13/1999

House, 112 Edwards Ferry Road

Current

County/Independent City: Loudoun

State: Virginia

Magisterial District: Leesburg

Tax Parcel: 48A-31-5

USGS Quad Map Name: LEESBURG

UTMs of Boundary:

Center UTM:

Restrict location and UTM data? N

ADDRESSES

Number

Thoroughfare Name

Explanation

112 -

Edwards Ferry Road

Current

42 -

Edwards Ferry Road

Number change

Vicinity:

Town/Village/Hamlet: Leesburg

Name of National Register Historic District:

Leesburg Historic District

Name of DHR Eligible Historic District:

Name of Local Historic District:

Old and Historic District

Physical Character of General Surroundings: Town

Site Description/Notable Landscape Features:

This house is built right up to the street with a fenced rear yard.

Ownership: Private

NR Resource Type: Building

WUZITS

Seq. #

of

Wuzit Types

Historic?

1.0

1

Single Dwelling

Historic

75.

1

Historic:

TOTAL:

1

Non-Historic:

PRIMARY RESOURCE EXTERIOR COMPONENT DESCRIPTION

mponent		#	Comp Type/Form	Material	Material Treatment
Chimney Door(s) Foundation Porch Roof Structural Window(s)	System	0 0 0 0 0	Interior end Single Leaf Solid 2-story, 3-bay Gable Masonry Sash, double-hung	Brick Wood Stone Wood Metal Brick Wood	Corbeled Cap Paneled Random Rubble Posts Standing Seam Flemish Bond 2/2

INDIVIDUAL RESOURCE INFORMATION

SEQUENCE NUMBER: 1.0

WUZIT: Single Dwelling

Primary Resource? Yes

Estimated Date of Construction: 1800-1895

Source of Date: Map

Site Visit

VDHR Survey File

Architectural Style: Federal

Other

Description:

The oldest part of this house is the 1-1/2-story, 4-bay, brick Federal-style portion dating from circa 1800. It has a Flemish bond facade with 5-course bond on the side elevations. The windows and door have brick jack arches. Around 1895, the house was raised to a full two stories with a frame second story. It has a gable roof and 2/2 sash. A substantial 4-bay, 2-story rear wing has a 2-story porch on the east.

Condition: Fair

Threats to Resource: None Known

Additions/Alterations Description:

This house is somewhat deteriorated and is now used as apartments.

Number of Stories:

Interior Plan Type:

Accessed? No If not, why not? Not accessible

Interior Description:

N/A

Relationship of Secondary Resources to Property:

None

DHR Historic Context: Architecture/Community Planning

Domestic

Significance Statement:

The street currently known as Edwards Ferry Road was historically a part of Market Street, one of the original roads of Leesburg as laid out in 1759. Market Street now takes a Y-bend southeast of Church Street. The part east of Church Street is no longer known as Market Street since it was renamed Edwards Ferry Road in the 1970s.) This street has historically contained the town's most important public buildings, and the county jail still remains within the project area. The road is depicted on the 1853 Yardley Taylor Map

of Leesburg with only a few buildings, including a jail, east of Church Street. The 1878 Gray's Map of Leesburg likewise shows only a few scattered houses along the northern side. By 1878, Market Street was also a through-way to Edwards Ferry Road, which crossed the Potomac River into Maryland approximately five miles east of Leesburg. The street contains a mix of residential architecture spanning several different periods, including at least three early-to-mid-nineteenth-century brick residences and the Johnston House/Tavern. By the late nineteenth century, the street was fully developed along its northern side and is marked by several handsome two-story frame Queen Anne and American Foursquare-style houses, several with original garages, outbuildings and fences. The south side has always been less developed, with the large Dodona Manor property dominating the east end of the street. This Federal-style building with a Vernacular addition at 112 Edwards Ferry Road is one of the oldest buildings on the street. The brick portion dates from the early 1800s. It appears on the 1853 Yardley Taylor, Gray's 1878 and the 1899-1937 Sanborn Maps of Leesburg. This building contributes to the architectural and historic character of the district in its scale, size, style and building materials.

GRAPHIC DOCUMENTATION

Medium Medium ID # Frames Date

B&W 35mm Photos 34 -17236 4/13/1999

BIBLIOGRAPHIC DATA

Sequence #: 1.0 Bibliographic Record Type: Map

Author: Sanborn Map Company

tation Abbreviation:

Fire Insurance Maps of Leesburg 1886-1937

Notes:

Sequence #: 2.0 Bibliographic Record Type: Map

Author: Gray, O. W. Citation Abbreviation:

Gray's New Map of Leesburg 1878

Notes:

Sequence #: 2.1 Bibliographic Record Type: Survey, DHR Author: Lewis, John (1972) and Hartzog, Lader & Richards (1975) Citation Abbreviation:


Reconnaissance-level architectural surveys of Leesburg Histo Notes:


CULTURAL RESOURCE MANAGEMENT EVENTS

Date: 12/17/1998

Cultural Resource Management Event: Reconnaissance Survey Organization or Person: Geoffrey Henry & Cheryl Shepherd ID # Associated with Event: CRM Event Notes or Comments:

MAILING ADDRESS







Construction Date Cir 1900 + 1945 Source In S	TOWN OF LEESBURG, VIRGINIA - Arch	hitectural-Historic Inventory Card
Present Owner: Richard Hardison, 140 Mailing Address: Rox III Present Use: Apartments Source John Construction Date on 1800 + 1845 Present Use: Apartments Source John Low 1845 Driginal Use: Builder/Architect Height in Stories Roof Form Gable Physical Description (materials): lor 1/12 Story brick cottage Raisad about the turn of the turn of the stories with the frame addition. Additions: Conferent attack. Note depth of reveal on 121 Mailtinos: Distinguishing Architectural Details: Exterior: Maition - pare Mailtinos: Type - Flat - roafed thed Architectural Significance: National State Local Photo: Roll 9 Negative 12 Physical Condition: Good Fair Poor Structure: Good Fair Poor	Street Address: 42 Edward Ferr	Tax Map: ARA Block: 3 Lot: 5
Style/Date Vermount Present Use: Apartments Source Inches India Construction Date or PROOF 1845 Source Inches India Builder/Architect Height in Stories Roof Form Gable Physical Description (materials): or 1/2 Story brick cottage raised about Re turn of the century to two full stories with a frame addition. Lor ferestration. Additions: Distinguishing Architectural Details: Exterior: Interior: Alterations: Architectural Significance: National State Local Architectural Significance: Details: Significant Contributory Roo Physical Condition: Structure: Good Fair Poor Structure: Grounds: Preservation Index: Construction Date of PROOF 1845 Source India Construction Date of PROOF 1845 Source India State Local Photo: Roll \$ 9 Negative 12 Physical Condition: Structure: Grounds: Preservation Index:		
Source Shin Law 1 Style Builder/Architect Builder/Architect Height in Stories Roof Form Gable Physical Description (materials): or 1/2 Story brids cottons raised about the turn-of-the century to two full story with a frame addition. Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of re	Mailing Address: Pox \\\	
Source Shin Law 1 Style Builder/Architect Builder/Architect Height in Stories Roof Form Gable Physical Description (materials): or 1/2 Story brids cottons raised about the turn-of-the century to two full story with a frame addition. Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of reveal on 121 Loop board. Conice returns on gable and. Note depth of re	Laurel Mal	
Builder/Architect Height in Stories Roof Form a ble Physical Description (materials): or 1/2 Story brick cottage raised about Re turn—of—the century to two full story with a frame addition. Loo ferestration. Additions: Distinguishing Architectural Details: Exterior: Interior: Alterations: Architectural Significance: National State Local Architectural Significance: National State Local Physical Condition: Contributory For Physical Condition: Structure: Good Fair Poor Structure: Grounds: Pereservation Index: Correservation	Prent Use: Aportments	
Physical Description (materials): or 1/2 Story brick cottage raised about the frame addition. The hum-of-the century to two full stories with a frame addition. It populates and the frame addition. Additions: or or or or or or or o		
Physical Description (materials): or 1/2 Story brick cottage raised about the turn of the century to two full stores with a frame addition. Confice returns on gable end. Note depth of reveal on 127 Additions: Distinguishing Architectural Details: Exterior: Interior: Alterations: Architectural Significance: National State Local Architectural Significance: Photo: Roll# 9 Negative 12 Outstanding Excellent Significant Contributory (20) Physical Condition: Structure: Good Fair Poor Structure: Good Fair Poor Structure: Grounds: Preservation Index: C	Original Use:	Height in Stories
Additions: Distinguishing Architectural Details: Exterior: Alterations: Alterations: Alterations: Alterations: Alterations: Alterations: Architectural Significance: National State Local Significance: Outstanding Excellent Significant Contributory Outstanding Excellent Significant Condition: Physical Condition: Good Fair Poor Structure: Good Fair Poor Structure: Grounds: Preservation Index: Contributory Contributo	Original Owner:	Roof Form gable
Distinguishing Architectural Details: Exterior: Alterations: Alterations: O' villdings: Type - Flat- roofed Shed Indition - part Antition - part Historic Significance: National _ State _ Local Architectural Significance: Outstanding _ Excellent _ Significant _ Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index: C	Physical Description (materials): \ The two -of-the century to two Clapboard. Cornice returns on oc Floor fenestration.	or 1/2 Story brick cottage raised about sfull stories with a frame addition. able end. Note depth of reveal on 15I
Distinguishing Architectural Details: Exterior: Alterations: Alterations: O' villdings: Type - Flat- roofed Shed Indition - part Antition - part Historic Significance: National _ State _ Local Architectural Significance: Outstanding _ Excellent _ Significant _ Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index: C	Additions:	
Interior: Alterations: Discription: Alterations: Discription: Another transfer of the decoration	Kent time all.	10.
Alterations: Discription: Alterations: Discription: Architectural Significance: Dutstanding Excellent Significant Contributory Physical Condition: Structure: Grounds: Neighborhood: Preservation Index:		<u>18</u> ;
Alterations: Ordination: Ordination: Ordination: Historic Significance: National State Local Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Structure: Grounds: Neighborhood: Preservation Index:	Date 1101 .	
Alterations: Ordination: Ordination: Ordination: Historic Significance: National State Local Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Structure: Grounds: Neighborhood: Preservation Index:		
Alterations: Ordination: Ordination: Ordination: Historic Significance: National State Local Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Structure: Grounds: Neighborhood: Preservation Index:		
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:	Interior:	
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:	Alterations:	
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		V Section 1
Architectural Significance: Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		Shed
Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		StateLocal
Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Outstanding Excellent Significant Contributory Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:	Architectural Significance:	Photo: Roll# 9 Negative 12
Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Physical Condition: Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		
Good Fair Poor Structure: Grounds: Neighborhood: Preservation Index:		in in the second
Structure: Grounds: Neighborhood: Preservation Index:		
Grounds: Neighborhood: Preservation Index:		
Neighborhood: Preservation Index:		
Preservation Index:		
191		
Comments:	Preservation Index:	
	Comments:	

Date: 12 75

MS

Filed By: